

This exploded view diagram illustrates the assembly of a hand tool, likely a brush cutter or trimmer. The components are numbered as follows:

- Main Body and Motor Assembly:** 1, 2, 3, 4, 5, 6, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29B, 30, 31, 32, 33, 34, 35, 36B, 37B, 38, 39, 40, 41B, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59B, 60, 61B, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75 for 4" Series, 76 for 5" Series, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108.
- Parts for 5" Wheel:** 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108.
- Parts for 4" Wheel:** 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108.
- Out-Type and In-Type Components:** 100, 101, 102, 103, 104, 105, 106, 107, 108.

2212